





ADJUSTMENTS







PROBLEM
DOOR DROPS
WHEN LET GO




BIT - PZ2/PH2




BALANCED




PROBLEM
DOOR RAISES
WHEN LET GO




BIT - PZ2/PH2




BALANCED




DOOR ADJUSTMENTS




COVER CAP



1



2




3


± 2 mm ± 2 mm ± 2 mm




REMOVAL



Warning



RISK OF INJURY FROM
SPRING-LOADED LEVER ASSEMBLY!



DO NOT PUSH
SPRING-LOADED LEVER
ASSEMBLY DOWN WITHOUT
A DOOR ATTACHED!

blum

